

SECRET

OUT-67609

1969 MAY 6 23 56Z

SECRET 062346Z MAY 69 CITE [] 6249

25X1
25X1

SUBJECT: YAW SLIT SMEAR

1. METHOD OF MEASURING YAW SLITS

- A. ZERO COMPARATOR ON MAJOR IMAGE POINT A. THE X, Y CO-ORDINATES OF POINT A WILL NOT BE RECORDED.
- B. MOVE TO MINOR IMAGE POINT B AND RECORD X, Y CO-ORDINATES.
- C. YAW SLIT AREAS TO BE MEASURED WILL BE SELECTED IN ACCORDANCE WITH THAT INDICATED IN REFERENCE CABLE.

2. ALL DATA WILL BE RECORDED ON CARDS AND SENT TO [] FOR [] WITH INFO COPY TO [] FOR PET MEETING.

25X1
25X1

3. CARD FORMAT, EFFECTIVE IMMEDIATELY, WILL BE AS FOLLOWS:

- COL. 1-4 MISSION NUMBER
- COL. 8-10 REV NUMBER RIGHT JUSTIFIED
- COL. 12-14 FRAME NUMBER RIGHT JUSTIFIED
- COL. 16 SMEAR SLIT IDENTIFIER
- ONE INDICATES DATA TRACK SIDE
- TWO INDICATES TITLE SIDE
- COL. 21-23 APPROXIMATE TIME FROM START OF FRAME TO MEASURED AREA TO THE NEAREST TENTH OF A SECOND.
- COL. 31 SIGN
- COL. 32-34 X VALUE (ACROSS TRACK) IN MICRONS (PLUS TOWARD TIME DATA TRACK)
- COL. 41 SIGN
- COL. 42-44 Y VALUE (ALONG TRACK) IN MICRONS (PLUS TOWARD OF FRAME)

SECRET

--END OF MESSAGE--

DISTRIBUTION		
	START	TIME
1	FILE	
	CABLE SEC.	
	FRAM/ED	
	SEC.	
23	TSO/PRO	
	PSG/OC	
	RBD	
	REFRO	
	AID	
	IEG	
	PROD	
	SCIEN	
	WEST	
	EAST	
	M&S	
	PCM	
	IAS	
	DIA-XX4	
	SPAD	
	DIA-AP	
	CMX	

25X1

SECRET

ADVANCE CY
SCHEDULED
Excluded from automatic
downgrading and
declassification